




Konami Concerto CPU

KP3.5 CPU MXM-II E8860
Refurbished

\$4,200.00

104510



I-Deck Tovis Button
Panel L1946BP2KN
Refurbished

\$2,569.44


100351



Power Supply PT# 192690
Konami Concerto
Refurbished

\$625.00


107593



27" LCD Bottom Monitor
Tovis OEM Monitor
Refurbished

\$435.00

102738



27" LCD Top Non-Touch
Tovis OEM Monitor
Refurbished

\$325.00

102737



Ceronix 27" Drop-In
Touch Lower
New Monitor

\$634.00

102660




Ceronix 27" Drop-In
Non-Touch Lower
New Monitor

\$528.00

102669

Concerto I-Deck Sensor Repair



Cost includes replacing frame, sensor glass, and flashing both AD Board and Touch Controller. Entire panel must be removed and sent to CasinoTech for service. Limited to quantity on-hand.

Need to replace the glass on your Concerto I-Deck Panel?

CasinoTech can replace your sensor and upgrade the frame to help prevent future breakage.

Only
\$400